



P.S:1.The attention please,if panel is the CMO or TOSHIBA.
The panel-bk right side need rubber washer 1mm.

AD/BOARD	2023L/2023-9906	MODEL	CM1205		泓瑜科技有限公司 WINSONIC TECH. CO., LTD.			
INVERTER	TIP017WS-01	PART NO.						
KEY PAD	PCBKEY019A0	MATERIAL	SECC	DATE	11/17/2008	APPROVED	DRAWN	JACK
PANEL:	AU-G121SN01 CMO-N121X5-L01 CMO-G121X1-L01 SHARP-LQ121S1DG61_SP_012706 TOSHIBA-LTD121LA#SG							REV. DWG SIZE